

00684.003600



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

HAJIME SEKIGUCHI ET AL.

Appl. No.: 10/787,079

Filed: February 27, 2004

For: IMAGE FORMING APPARATUS

U.S. Patent No.: 7,009,158 B2

Issued: March 7, 2006

)
:
) Examiner: Quang T. Van
:
) Group Art Unit: 3742
:
) Confirmation No.: 4303
:
)
:
)
:
)
:
)
:
) June 28, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
JUL 03 2006
of Correction

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

06/29/2006 SZEWDIE1 00000071 7009158

01 FC:1811

100.00 OP

2006

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Lawrence A. Stahl
Attorney for Patentees
Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,009,158 B2

DATED : March 7, 2006

INVENTOR(S) : HAJIME SEKIGUCHI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 21, "comprising" should read --comprises--.

COLUMN 5:

Line 56, "1, com" should read --1 com--.

COLUMN 6:

Line 32, "or" should read --of--.

COLUMN 9:

Line 55, "bear" should read --gear--.

COLUMN 14:

Line 24, "or" should read --of--.

COLUMN 15:

Line 54, "bear 18)." should read --gear 18).--.

COLUMN 17:

Line 21, "servicing" should read --service--.

COLUMN 19:

Line 63, "corresponds" should read --corresponds to--.

COLUMN 20:

Line 12, "goes" should read --go--.

Line 16, "that" should read --that of--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,009,158 B2

No. of add'l. copies
@ 30¢ per page



Sub

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,009,158 B2

DATED : March 7, 2006

INVENTOR(S) : HAJIME SEKIGUCHI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 7, "minimize" should read --minimizes--.

Line 25, "shown" should read --shows--.

Line 49, "that" should read --that of--.

COLUMN 24:

Line 6, "3r and 3a" should read --3r and 3s--.

line 19, "3r and 3h," should read --3f and 3h,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,009,158 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,009,158 B2

DATED : March 7, 2006

INVENTOR(S) : HAJIME SEKIGUCHI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 21, "comprising" should read --comprises--.

COLUMN 5:

Line 56, "1, com" should read --1 com--.

COLUMN 6:

Line 32, "or" should read --of--.

COLUMN 9:

Line 55, "bear" should read --gear--.

COLUMN 14:

Line 24, "or" should read --of--.

COLUMN 15:

Line 54, "bear 18)." should read --gear 18).--.

COLUMN 17:

Line 21, "servicing" should read --service--.

COLUMN 19:

Line 63, "corresponds" should read --corresponds to--.

COLUMN 20:

Line 12, "goes" should read --go--.

Line 16, "that" should read --that of--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,009,158 B2

No. of add'l. copies
@ 30¢ per page



4006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,009,158 B2

DATED : March 7, 2006

INVENTOR(S) : HAJIME SEKIGUCHI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 7, "minimize" should read --minimizes--.

Line 25, "shown" should read --shows--.

Line 49, "that" should read --that of--.

COLUMN 24:

Line 6, "3r and 3a" should read --3r and 3s--.

line 19, "3r and 3h," should read --3f and 3h,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,009,158 B2

No. of add'l. copies
@ 30¢ per page

